Information Sheet 470a

Planning and Application Description

Planning and application, checklists for the system application of Floortec 2C Mineralico SL 470



General planning instructions

- This document should be made accessible to all those participating in the coating procedure, so that everyone is informed about the procedure and the individual steps. Only in this way can a flawless process sequence be ensured.
- If feasible, the installation of the flooring plaster system should be scheduled in the project planning to take place after all other work segments, or as close to the end as possible, to prevent mechanical damage.
- A time window of 4-7 work days should be slated for performing the essential work steps of the system build-up.
- Allow extra time for additional work, such as preliminary filling, etc. (for the implementation as well as for extended drying times).
- The surfaces may be walked on carefully about 12 hours after completion of the 2C PU Sealing. The complete curing of 2C PU Sealer takes 7 days.
- If the finished surfaces are to be covered, this must be done with water vapor permeable covering materials such as felt board or nonwoven without film lamination, in order to avoid impairing the curing process of the mineral filler material and to prevent possible moisture accumulation under the covering material.
- During the implementation period, other craftspeople should avoid the rooms being coated, and the surfaces should be protected against dust or dirt contamination.
- In case of heated floor constructions, the floor heating is to be turned off at least 3 days before the onset of work or lowered to no more than +15 to 18°C. It may only be restarted 7 days after system application at the earliest.
- In particular, pay attention to the minimum drying times and individual residual moisture in newly created or soon to be created screed surfaces.
- Even beforehand, observe room, substrate, and material temperatures.
- Take measures to prevent direct incidence of sunlight onto the surfaces to be treated through large window fronts or floor-level windows. Close venetian blinds or cover window fronts.

Brilluxmehrals Farbe

Date: 20.03.2018 Page 1 of 12

Construction site equipment

- If possible, examine and, as appropriate, prepare the tools and equipment required for the particular work step one day in advance.
- Also ready the needed materials in due time and check for adequate quantities.
- Equip the mixing place such that a flawless process sequence for mixing and transporting the material to the installation site is ensured.
- Apply tinted 2C Mineralico SL 470 within 2 weeks. If the product is applied later, it must be reshaken.

List of materials and tools

The required materials and tools are to be provided in due time and in sufficient quantity.

Materials	Article number	Consumption (per application)	Com- pleted		
Priming with					
Multi Floor Primer LF 3084	3084.0005	50-80 g/m² undiluted material			
or Special Primer LF 3085	3085.0005	100-150 g/m²			
Filling with					
Floor Leveling Compound 3115	3115.0025	4,5 kg/m² with 3 mm film thickness			
or Floor Leveling Compound FX 3109	3109.0025	4,5 kg/m ² with 3 mm film thickness			
Perimeter Insulation Strips SK 3018 (optional)	3018	as required			
Facade Smoothing Filler F 1539 (optional)	1539.0004	as required			
Double intermediate priming with	Double intermediate priming with				
Multi Floor Primer LF 3084	3084.0005	2x 50-80 g/m² undiluted material			
Create the plaster floor with					
Floortec 2C Mineralico SL 470 mixed with	0470.0020	4,5–5 kg/m² prepared mixture, incl. hardener			
Floortec Hardener 471	0471.0005				
Priming with	Priming with				
Floortec 2C Epoxy Primer 473 mixed with	0473.0002	Ca. 85 ml/m ²			
Floortec Epoxy Hardener 849	0849.0500	prepared mixture			
Double sealing with					
Floortec 2C PU Sealer 474	0474.5,5	2x 50 ml/m ² prepared mixture			



List of materials and tools

Tools and accessories

Designation	Article number	Consumption	Com- pleted
Collomix mortar mixing tool DLX 152 HF	3347.0152	1 unit per application team	
High-performance stirrer at least 1,300 W e.g., Collomix mixer Xo 4	3347.0004.	1 unit per application team	
Collomix coupling HEXAFIX®/M14 exterior	3347.0015	optional depending on stirrer	
Festool 2K Stirring Rod 1841	1841.0120	optional depending on stirrer	
Adapter for HEXAFIX® stirrers	1841.0300	optional depending on stirrer	
	1828.0025		
Surface filler knife (size 25, 40 or 50 cm wide)	1828.0040	1 unit per application team	
(0.10 20, 10 01 00 0	1828.0050	100	
Broom and apparatus handle	1348.0140	1 unit per application	
with handle socket	1347.0000	team	
Metal floor squeegee, height-adjustable incl. handle socket	1324.0560	1 unit per application team	
Double-edge Notched Blade TKB R2 (for 3115)	1326.0028.0012	2 units per application team	
Double-edge Notched Blade TKB R3 (for 470)	1326.0028.0013	2 units per application team	
De-aerating roller	1137.0026.0000	1 unit per application team	
Spiked screed soles, blunt	1196.0001	2 pairs per application team	
Overshoes	1846.0000	as required (pack of 20)	
Vacuum cleaner, e.g., Festool dust extractor CTL MIDI with Cleaning set for tradesmen D 36	3479.0000		
HW RS Plus	3424.0008		
Perimeter Insulation Strip SK 3018	3018.0025	Dependent on the room	
Short-fiber paint roller	1217.0025	1 unit per application team	
Microfiber paint roller	1221.0025	1 unit per application team	
Rotary disk sanding machine	3694.0000	-	
Driving plate for the sanding-pad attachment for the rotary disk sanding machine	3694.0020	1 unit per sanding machine	
Sanding pad, green for rotary disk sanding machine	3694.0400.0001	1 unit per 100 m ²	
Bucket trowel, 10 cm	3782.0010	1 unit per application team	
Stop watch or timer	-	1 unit per application team	



Personnel planning and allocation

- An adequate number of workers for the individual work steps is crucial for the success of the coating procedure.
- In particular, floor-coating tasks are usually limited by tight scheduling. When the performance deadlines have been set, substitute personnel should be available on call in case of need.
- The following tables can serve as a rough orientation for personnel requirements. A site-oriented planning is indispensable, for example in complexly partitioned areas.

Recommended minimum number of workers for the leveling with filler

Size	Total number of workers	For mixing and transport	For creating a textured surface and leveling
Up to approx. 100 m ²	3	2	1
Up to approx. 200 m ²	5	3	2
Up to approx. 500 m ²	7	4	3
Up to approx. 1000 m ²	9	5	4

Recommended minimum number of workers for applying 2C Mineralico SL 470

Size	Total number of workers *	For mixing and transport	For creating a textured surface and leveling	For re- smoothing/ design
Up to approx. 100 m ²	4	2	1	1
Up to approx. 200 m ²	7	3	2	1–2
Up to approx. 500 m ²	9	4	3	2
Up to approx. 1000 m²	12	5	4	2–3

^{*} The data pertain to the single-colored implementation. In case of a two-colored implementation, schedule 1 to 2 additional persons in each case.

Recommended minimum number of workers for the priming and sealing

Size	Total number of workers
Up to approx. 100 m ²	1–2
Up to approx. 200 m ²	2–3
Up to approx. 500 m ²	3–4
Up to approx. 1000 m ²	4–5



Detailed planning for applying Floortec 2C Mineralico SL 470

- Particularly for complex, e.g. contorted, surfaces, allocate the personnel such that the surfaces can be coated smoothly and expeditiously.
- The application paths of several application teams must be planned such that the work can always be done wet in moist. Pay attention to the open time (max 15 min, depending on site conditions), especially when re-smoothing.
- Processing teams of two persons each are recommended in principle for the application and the smoothing procedures; they are provided with mixed material by one or two persons, respectively.
- Depending on the object, it is advisable to prepare a drawing of the respective room and to allocate the teams and jointly determine the implementation process based on this drawing.

Implementation process
Sketch of the respective room for the planning of the application paths, application course, and design orientation

Before beginning the coating work

Figure	Description	Note
	Inspection of the substrate Inspect the substrate load-bearing capacity and cracks.	
	Inspection by means of visual inspection, crack inspection, moisture measurement, adhesive-strength inspection, etc. Expansion joints must be retained. Clearly mark the beginning and end points of the joints on the walls.	
	Follow the instructions on surface preparation in the Data Sheets for the system products.	

Day 1: Leveling of the floor surfaces with filler

Day 1: Leveling of the floor surfaces wit Figure	Description	Note
	Vacuum and clean prepared floor surfaces. Apply Perimeter Insulation Strips SK 3018.	
Brillux	Priming depending on the substrate with Multi Floor Primer LF 3084 (1:3 with water) or Special Primer LF 3085.	New screeds can exhibit increased absorbency, such that they should be primed 2x where required to avoid potential pore formation in the subsequent leveling with filler to the greatest possible extent.
	Mix Floor Leveling Compound 3115 or Floor Leveling Compound FX 3109 with a suitable stirrer and stirring rod until it is lump-free. Preferably, use the Collomix mortar mixing tool DLX 152 HF 3347.	Ensure that the correct quantity of water, 5.5 liters/25 kg, is added. Use a measuring bucket. Allow to stand for at least 3 minutes, then stir again before application.
	Filling: Spread Floor Leveling Compound 3115 (Metal Floor Squeegee 1324 with Double-edge Notched Blade TKB R2) using a squeegee. Spread Floor Leveling Compound FX 3109 evenly with the Metal Floor Squeegee 1324 (without notched blade) or the Stainless Steel Trowel 3792.	In a layer at least 3 mm thick
	Work over the fresh leveling layer in transverse directions (once horizontally and once vertically) with the de-aeration roller	

Day 2: First part - intermediate priming with Multi Floor Primer LF 3084

Figure	Description	Note
	Inspect the substrate (implemented leveled filling)!!!	Always pay attention to the residual moisture of the leveling layer (film test 15 minutes) For the further build-up, sand the filled surfaces beforehand (grain size P60/P80) and then vacuum them.
	Fill existing pores with Facade Smoothing Filler F 1539. Intermediate drying with this processing method approx. 60 minutes or over night.	In the process, scrape the trowel across the surface with exerted pressure. This pore filling is also possible after intermediate priming. However, the filled areas must then be primed again.
	Intermediate priming: 2-fold priming with Multi Floor Primer LF 3084 (diluted 1:1 with water).	Apply with Short Fiber Paint Roller 1217, preferably in alternate directions. Avoid creating imperfections, apply evenly.
Brillux 2x-Mineralico St 470	Mix Floortec 2C Mineralico SL 470 with Hardener 471. Use a mixer with at least 1,300 watts of power. Use Collomix mortar mixing tool DLX 152 HF or alternatively employ a double stirrer.	Stirring time: 2 minutes. Use a stop watch or timer. Remove possibly dried-out cement residue from the container rims with the trowel. Ensure that the components are mixed completely and that the mixture is free from lumps.



Day 2: Second part - application of Floortec 2C Mineralico 470 SL

Figure	Description	Note
	Coating: Always pour all of the mixed material out of the respective containers immediately.	The mixed material cures in the container within a few minutes and can then no longer be applied. For the smallest areas, inlay work, etc., weigh out the required partial quantities.
	Spread Floortec 2C Mineralico SL 470 using a squeegee. Metal Floor Squeegee 1324 with Double-edge Notched Blade TKB R3.	Always work over the surfaces with the squeegee completely and avoid material accumulations.
	Re-smooth (texture) the spread filler material with a Surface Filler Knife 1828 with handle socket or a Venetian Trowel 1764 to create an individual design. It is best to work in a diagonal direction. Do not level at right-angles or in lines. The flooring professionals should wear spiked screed soles, blunt.	Re-smooth material dripping off of the surface filler knife; drip marks remain visible after drying. After approx. 2 hours, the surfaces can be carefully walked on wearing socks and overshoes, for example, in order to remove masking tape. Protect surfaces to prevent them being walked on by unauthorized persons (cordon off the area)



Day 3: First part - remove perimeter insulation strips, vacuum and polish surfaces

Day 3: First part - remove perimeter insulation strips, vacuum and polish surfaces			
Figure	Description	Note	
	Use a utility knife to cut the perimeter insulation strips flush with the floor surface and remove them.		
	After-treatment: Vacuum surfaces. Utilize hard-floor/brush adapter.		
	Polish surfaces with rotary disk sanding machine and green pad.	Alternatively, difficult-to- access areas, small surfaces, and inner corners can be polished with the Rotex or by hand with a green pad.	
	Vacuum the surfaces again as required.		

Day 3: Second part - prime surfaces with 2C Epoxy Primer 473

Figure	Description	Note
	Priming: Prepare the 2C Epoxy Primer 473 in accordance with the instructions and allow to pre-react for 10 minutes. Apply in a thin layer in transverse directions (once horizontally and once vertically) and distribute and smooth uniformly with the Microfiber Paint Roller 1221. Avoid flaws. Never thin the epoxy primer! Avoid roller edges and surplus material. Observe the consumption data. Carry out any trimming works in the course of the surface treatment. The surfaces can be recoated after approx. 12–18 hours.	

Day 4: Sealing with Floortec 2C PU Sealer 474

Figure	Description	Note
	Sealing: Apply Floortec 2C PU Sealer 474 in an interval of about 2 to 3 hours in accordance with the relevant instructions twice with the Microfiber Paint Roller 1221.	The application of the material takes place in ca. 1 m wide strips transverse to the main direction of incident light. The still-wet surface material is then rolled out evenly in only one direction toward the light.
	Walk on the surfaces only with a clean shoe-sole tread and overshoes. Dirt contamination results in damage to the newly created surfaces.	Complete both work steps within 12 hours. If not possible perform intermediate sanding with an abrasive disc for PU coatings.

Notes

Cleaning and Maintenance instructions

After completion of the work and acceptance of the surfaces by the user, the Cleaning and Maintenance Instruction - Information Sheet 470p - must be given to the customer. By handing over these cleaning and care instructions, the flooring professional is in compliance with his or her obligations in accordance with DIN 18365.

Further information

Follow the instructions on the Data Sheets of the products used.



Remark

This planning and application description is based on intensive development work and many years of practical experience. The contents do not form a legal contract. The user and/or the purchaser is not released from the responsibility of checking that our products are suitable for the proposed use. In addition our Terms of Conditions and Payment apply.

When a new version of this Data Sheet appears with updated information the previous version no longer applies. The current version is available on our website.

Brillux Weseler Straße 401 48163 Münster GERMANY Phone +49 251 7188-0 Fax +49 251 7188-105 info@brillux.de www.brillux.com

